


1.- PHYSICS

1.1. 3D PHYSICS



Sets (sensor + elements + supervisory software) required for each study

Sensor + Elements



Supervisory Software (+)

FCE. Electric Fields Study Set


Sensor + Elements



Supervisory Software (+)

FCM. Magnetic Field Study Set

Sensor + Elements



Supervisory Software (+)

FM. Mechanics Study Set

Sensor + Elements



Supervisory Software (+)

FAC. Acoustics Study Set


Sensor + Elements



Supervisory Software (+)

FOP. Optics Study Set

Sensor + Elements




Supervisory Software (+)

FTT. Thermodynamics Study Set


1.- PHYSICS

SOFTWARE SCREENS EXAMPLES:


FCE
Electric Fields Study Set




FM
Mechanics Study Set




FOP
Optics Study Set



FCM
Magnetic Field Study Set



FAC
Acoustics Study Set



FTT
Thermodynamics Study Set

